Industry





CAL) Adjusting program (CAL): For quick setting of the balance's accuracy. External adjusting weight required.

AKU Rechargeable battery pack: rechargeable set.



â

Mains adapter: 230 V/50Hz in standard version for Germany. On




TAR Tare: put back displayed value to "0" during weighing process, e.g. to add or remove weighing material from a container.



Crane scale





Service